




PCN#	PCN20250325-010	PCN ISSUE DATE	May 25, 2025												
PCN TITLE SKU#109100021, L76K GNSS Module for Seeed Studio XIAO															
REVISION		CUSTOMER CONTACT													
TYPE OF CHANGE ☐ Electrical Specification ☐ Mechanical Specification ☐ Firmware Specification ☐ Regulatory of Compliance ☐ Part Number ☐ End of Life ☒ Other															
AFFECTED PART NUMBER(S) <table border="1" style="width: 100%;"> <thead> <tr> <th>Part Number</th> <th>Name</th> </tr> </thead> <tbody> <tr> <td>109100021</td> <td>L76K GNSS Module for Seeed Studio XIAO</td> </tr> </tbody> </table>				Part Number	Name	109100021	L76K GNSS Module for Seeed Studio XIAO								
Part Number	Name														
109100021	L76K GNSS Module for Seeed Studio XIAO														
CHANGE DESCRIPTION Change FROM: <table border="1" style="width: 100%;"> <thead> <tr> <th>Part Number</th> <th>Name</th> <th>Image</th> </tr> </thead> <tbody> <tr> <td>109100021</td> <td>L76K GNSS Module for Seeed Studio XIAO</td> <td></td> </tr> </tbody> </table> Change TO: <table border="1" style="width: 100%;"> <thead> <tr> <th>Part Number</th> <th>Name</th> <th>Image</th> </tr> </thead> <tbody> <tr> <td>109100021</td> <td>L76K GNSS Module for Seeed Studio XIAO</td> <td>  U.FL Receptacle For Active GNSS Antenna Sink current limit: 50mA Quectel L76K Reset [Normal] RESET Sleep [Normal] WAKEUP 3V3 5V GND </td> </tr> </tbody> </table>				Part Number	Name	Image	109100021	L76K GNSS Module for Seeed Studio XIAO		Part Number	Name	Image	109100021	L76K GNSS Module for Seeed Studio XIAO	 U.FL Receptacle For Active GNSS Antenna Sink current limit: 50mA Quectel L76K Reset [Normal] RESET Sleep [Normal] WAKEUP 3V3 5V GND
Part Number	Name	Image													
109100021	L76K GNSS Module for Seeed Studio XIAO														
Part Number	Name	Image													
109100021	L76K GNSS Module for Seeed Studio XIAO	 U.FL Receptacle For Active GNSS Antenna Sink current limit: 50mA Quectel L76K Reset [Normal] RESET Sleep [Normal] WAKEUP 3V3 5V GND													
REASONS FOR CHANGE Considering the scenario of power saving, we removed the fix status indicator.															
CUSTOMER ACTION REQUIRED /															