seeed studio

INDUSTRIAL PRODUCT DATASHEET

SenseCAP M4 based on reComputer - X86 Development Board (J4125-08-00-512SSD) V2.0 (With Fan)

SenseCAP M4 based on reComputer - X86 Development Board (J4125-08-00-512SSD) V2.0 (With Fan) with BIOS access and a firmware flashing guide for other applications after discontinuing Flux and MystNode support.

SKU	UPDATED	PRICE
110991865	2026-09-19 03:17:59	$299.00(Excl. VAT)



Overview



The SenseCAP M4 based on reComputer - X86 Development Board (J4125-08-00-512SSD) V2.0 (With Fan) no longer supports Flux or MystNode, and Helium has changed its reward mechanism. A step-by-step firmware flashing guide is provided for customers who would like BIOS access for other applications.

Key Features

Note:

As this device no longer supports Flux or MystNode, and Helium has changed its reward mechanism, we have received many requests from customers who would like BIOS access for other applications. We have therefore provided a step-by-step firmware flashing guide. Please click **here** for reference.

Product Gallery















Compliance & Logistics

HSCODE	8517629990
USHSCODE	8517620010
UPC	
EUHSCODE	8517180000
COO	CHINA

FCC Requirement

Any changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

(1) this device may not cause harmful interference, and

(2) this device must accept any interference received, including interference that may cause undesired operation.

15.21

This transmitter must not be co-located or operating in conjunction with any other antenna or transmitter.

Note: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules.

These limits are designed to provide reasonable protection against harmful interference in a residential installation.

This equipment generates, uses, and can radiate radio frequency energy.

If not installed and used in accordance with the instructions, it may cause harmful interference to radio communications.

However, there is no guarantee that interference will not occur in a particular installation.

If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Resource Links

- https://www.seeedstudio.com/SenseCAP-M4-p-5556.html

Seeed Technology Co.,Ltd.
9F, Building G3, International E City,
Zhongshanyuan Road, Nanshan, Shenzhen, China

Tel: +86 0755-80695676
Web: www.seeed.cc
Shop: www.seeedstudio.com